

2013 Honda STEPWAGON 2.0 Spada Z		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RK5	DISPLACEMENT 1,997 cc		
YEAR / REG. 2013/11	MILEAGE 136,000 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. RK5-1358128	DIMENSIONS (L X W X H) 469 × 170 × 182 cm		
SALES POINTS			
Alloy Wheels Front Camera		Power Sliding Doors (Both Sides) (Both... Navigation System	
INSPECTOR REPORT			
Interior/exterior light scratches A. Navigation touch panel faulty.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/11月	メーカー ホンダ	ドア枚数 5	ボディ形式 ミニバン/ワンボックス	駆動方式 2WD	グレード 2.0 スパーダZ 両側電動 スライド 9インチナビ	登録区分 4WD	年 4
車種 自家用・その他 ()	排気量 2000 CC	型式 DBA-RK5	通称 ミニバン	内装 A・B・C	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書等)
年 9	月 1	日 1	抹消 インパネ	CVT	走行 136,000 km	マイル 000	色 黒
外装色 プレミアムスパークルブラックパール	カラーNo. ()	内装色 ()	乗車定員 8人	リサイクル料 13,840円	登録料 13,840円	預託料 13,840円	整備品のみ O印 を記入
セールスポイント キーレスエントリー/A B S/運転席エアバック/助手席エアバック/メモリーナビ他ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/H I D・キセノン・ディスチャージ/横滑り防止装置 (E S C) /3列シート/フルフラット/D V D 再生/C D/バックカメラ/M Tモード付き/両側電動スライドドア				修理歴 有 .			
特記事項 両側電動スライド★9インチナビ★バックカメラ★ETC★フリップダウンモニター★パドルシフト★横滑り防止装置★レザー調シートカバー★スモークフィルム★社外19AW★オートライト★HID★フォグ★				検査記入欄 内外装ウス ナビタッチパネル不良			
検査項目 FW トビ石 傷A ワレ 外装 小 A・U A・曲 ホイル エアロ シリアル No. 車種 年式 色 最大荷重量 Kg				A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換済			