

2013 Honda STEPWAGON SPADA Z Cool Spirit		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
RK5	1,997 cc		
YEAR / REG.	MILEAGE		
2013/10	133,761 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Purple	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
RK5-1365866	469 × 170 × 182 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Cruise Control		Navigation System	
INSPECTOR REPORT			
Light interior stains			

ORIGINAL JAPANESE AUCTION SHEET

H25 / 10月		ホンダ		5	ミニバンワンボックス		4																				
ステップワゴンスパダ Z		クールスピ		リット																							
車種	白銀用 ・ その他 ()	排気量	2000 CC	型式	RK5	通称	A・B・C																				
車検	- - 年 - - 月 - - 日	燃料	ガソリン	ディーゼル		後日選り込み (保証書・取扱説明書等)																					
走行	133,761 km	フロア	AT																								
外装色	プレミアムスパークルブラックパール	カラーNo.		装備品のみ O印 を記入																							
内装色		乗車定員	7人	サンルーフ 革シート																							
左・前・後	ディーラー	走行	13,840円	エブリック																							
セールスポイント																											
検査記入欄				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/ヘコ</td><td>P</td><td>色あせ/サケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/サケ	G	ガラスキズ																		
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																		
室内汚損				<table border="1"> <tr> <td>登録No.</td> <td colspan="3">月 日</td> <td colspan="2">名 宛 中</td> </tr> <tr> <td>車体番号</td> <td colspan="5">RK5-1365866</td> </tr> </table>				登録No.	月 日			名 宛 中		車体番号	RK5-1365866												
登録No.	月 日			名 宛 中																							
車体番号	RK5-1365866																										
FW	トピ石	備A	ワレ	外装	小	ホイール	エアロ																				
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ	スレ																				
				長さ	幅	高さ	最大積重量																				
				cm	cm	cm	kg																				