


2013 IS 2.5 IS250		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GSE30	DISPLACEMENT 2,499 cc		
YEAR / REG. 2013/10	MILEAGE 59,518 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. GSE30-5018949	DIMENSIONS (L X W X H) 466 × 181 × 143 cm		
SALES POINTS			
Alloy Wheels Cruise Control Lexus IS Premium Sound System (8 sp...		Leather Seats Navigation System	
INSPECTOR REPORT			
Front windshield has scratches, stone chips, cracks, and repair marks, requiring repair or replacement. Interior has scratches, dirt, burns, holes, scuffs, and tears.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成25.10月	車名・グレード IS IS250	2WD 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-GSE30	排気量 2500 CC	ドア 4 形状 SD
		定員 5人 積載 kg	外装 内装 B B
車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限ります)	
車検 年 月 (日)	冷却 AAC	スマートキー・ETC・HJDヘッドライト	
走行 5万9千518 km	燃料 ガソリン	パワーシート・パワーステアリング・クルーズコントロール	
色 シルバー	色替 色コード 1J4	装備品 (純正品に限り○をつけてください)	
R券 12,980 円		(P)S (P)V (A)B (A)B (A)V	
注意事項申告欄		S R ナビ TV カワ	
外装 小A・小U		新車保証書 後日品	
		有・無	
			
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ	A-キズ E-エケボ U-凹み W-補修跡 S-サビ O-腐食 XX-交換済	
車台番号 5018949		型式指定番号 17522	車検有効年月 0001
登録番号		全長 466 mm	全幅 181 mm
		全高 143 mm	