

2013 IS 2.5 IS250 Version L		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GSE30	DISPLACEMENT 2,499 cc		
YEAR / REG. 2013/09	MILEAGE 72,845 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. GSE30-5013956	DIMENSIONS (L X W X H) 466 × 181 × 143 cm		
SALES POINTS			
Sunroof Leather Seats Navigation System		Alloy Wheels Cruise Control Lexus IS Premium Sound System (8 sp...	
INSPECTOR REPORT			
Exterior has minor scratches and dents. Aftermarket 19-inch aluminum wheels, coilovers, and muffler installed. Front windshield has scratches, stone chips, cracks, and repair marks; replacement recommended. Interior shows scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成25年 9月	車名・グレード IS IS250ハーツェンL	2WD 4WD	評価点 (4.5)
ディーラー・並行 型式 DBA-GSE30	排気量 2500 CC	ドア 4 形状 SD	定員 5人 積載 kg
モデル年式 年 ハンドル 左・右	外装 B	内装 B	
車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)	
車検 年 月 (日)	冷暖 AAC	スマートキー・会社外アルミホイール・ETC	
走行 7万2千845 km	燃料 ガソリン	HIDヘッドライト	
色 レッド	色コード 3R1/LA20	Bluetooth音楽再生、クルーズ、エアシート	
R券 12,980 円		諸備品 (純正品に限り○をつけてください)	
注意事項申告欄		(P) (PW) (BS) (AB) A W (S) ナビ TV カワ	
外装 小A・小U		新車保証書 未日品	
社外19アルミ		有・無	
社外車高調			
社外マフラー			
フロントガラス キズ・ヒビ割・リペア跡・X要			
内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ			
車台番号 5013956		A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済	
登録番号		型式検査番号 17522 識別区分番号 0003	
		全長 466mm 全幅 181mm 全高 143mm	