

2013 LEXUS IS IS250 Version L Sunroof Leather Seat ETC Seat Heater Back Camera		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GSE35	DISPLACEMENT 2,499 cc		
YEAR / REG. 2013/10	MILEAGE 83,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Sedan		
CHASSIS NO. GSE35-5006076	DIMENSIONS (L X W X H) 466 × 181 × 143 cm		
SALES POINTS			
Alloy Wheels Leather Seats Cruise Control Navigation System		Sunroof Power Seats (Front) Back Camera Lexus IS Premium Sound System (8 sp...	
INSPECTOR REPORT			
Front windshield has a B-grade chip. Seats are scuffed and dirty. Steering wheel is scuffed.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H25 10月	メーカー レクサス	ドア数 4	ボディ形状 セダン	評価点 4.5
車名 IS	グレード IS 250バージョンL ★レザーシート★ETC★ナビ★バックカメラ★	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 2500	形式 DBA-GSE35	国産 A・⑨・C	
年 8	月 10	日 0	扶養 0	ディーゼル 0
走行 83,000	フロア 6	AT	後付選り品 ()	
外装色 パール	カラーNo. 077	エンジン AG・WAG・ ()	装備品のみ・C印を記入	
内装色 ()	乗車定員 5人	5人	EP	EP
左・ ()	ディーラー 12,980	走行 12,980	EP	EP
セールスポイント				
サンルーフ・レザーシート・ETC・シートヒーター・バックカメラ・クルーズコントロール・パワーシート・ドラレコ・純正ナビ・フルセグTV・純正フロアマット・純正AW・横滑り防止装置・盗難防止装置・CD/DVD再生・4WD・MTモード付・ディスチャージドランプ・フロントフォグランプ・ABS・Bluetooth接続				
検査記入欄				
・フロントガラス トビB ・シートスレ、汚れ ・ハンドルスレ				
車検 有・⑥				
名義中				
月 日				
GSE35-5006076				
466 181 143				