

2013 MAZDA ATENZA WAGON XD_L Package		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GJ2FW	DISPLACEMENT 2,188 cc		
YEAR / REG. 2013/10	MILEAGE 134,881 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. GJ2FW-108097	DIMENSIONS (L X W X H) 480 × 184 × 148 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Pre-Collision Braking Navigation System		Roof Rails Leather Seats (Perforated Leather) Adaptive Cruise Control Bose Sound System with AUDIOMPILOT ...	
INSPECTOR REPORT			

初年度登録		メーカー		マツダ		ドア数		5		ボディ形状		評価点																																																									
H25 / 10月		車名		アテンザワゴン		グレード		XD-Li [※] サージ		駆動方式		4WD																																																									
車種		自家用・その他 ()		排気量		2200		型式		GJ2FW		内装																																																									
車検		8 年 10 月 / 扶消		登録		ガソリン		変速機		オートマ		後付部品 ()																																																									
走行		134,881 km		シフト		フロア		AT		車検		後付部品 ()																																																									
外装色		アゲ		カラーNo.		428		エンジン		AG・BG・WAG・()		後付部品 ()																																																									
()		内装色		グレー系		標準塗装		5 人		PS		PW																																																									
左・右		ディーラー		走行		12,540 km		ABS		TV		エレクトロニクス																																																									
セールスポイント																																																																					
検査記入欄		<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ</td> <td>ヤレ</td> <td>B</td> <td>キズ</td> <td>H</td> <td>20</td> <td>色あせ</td> <td>ベタ</td> <td>G</td> <td>ガラス</td> <td>キズ</td> </tr> <tr> <td>W</td> <td>補修跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換</td> <td>XX</td> <td>交換</td> <td>XX</td> <td>交換</td> <td>XX</td> <td>交換</td> </tr> <tr> <td>登録No.</td> <td colspan="2">三河</td> <td colspan="2">301</td> <td colspan="2">も</td> <td colspan="2">7039</td> <td colspan="2">名義</td> <td colspan="3">日 家で名義である</td> </tr> <tr> <td>車検番号</td> <td colspan="13">GJ2FW-108097</td> </tr> </table>												A	キズ	U	へこみ	ヤレ	B	キズ	H	20	色あせ	ベタ	G	ガラス	キズ	W	補修跡	S	サビ	C	腐食	X	交換	XX	交換	XX	交換	XX	交換	登録No.	三河		301		も		7039		名義		日 家で名義である			車検番号	GJ2FW-108097												
A	キズ	U	へこみ	ヤレ	B	キズ	H	20	色あせ	ベタ	G	ガラス	キズ																																																								
W	補修跡	S	サビ	C	腐食	X	交換	XX	交換	XX	交換	XX	交換																																																								
登録No.	三河		301		も		7039		名義		日 家で名義である																																																										
車検番号	GJ2FW-108097																																																																				
FW		トビ石		傷A		フレ		外装		小		ホイル		エアロ																																																							
内装		正色		シロ		ヤブレ		コガ		コガ		オーデ		スレ																																																							
車検		480 cm		184 cm		148 cm		最大積載量																																																													