

2013 Mazda Carol ECO ECO X 4WD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-HB35S	658 cc		
YEAR / REG.	MILEAGE		
2013/04	84,727 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Other		
CHASSIS NO.	DIMENSIONS (L X W X H)		
HB35S-102665	339 × 147 × 153 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Front windshield stone chip, interior scratches, dirt, scuffs, interior odor, underbody rust paint			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	17458	車両区分番号	0601	シリアル番号		評価点	
初年度登録	H 25	年	4	月	車名	キャロル	グレード	ECO X 4WD	3.5
型式	DBA-HB35S	排気量	660 cc	燃料	ガソリン	駆動	4WD	内装	A B C
車種	乗用車	年	2013	月	4	車歴	727 km	シフト	CVT
走行距離	84,727 km	マイル	53,400	キロ	53,400	キロ	53,400	キロ	53,400
外装色	元色	エボニー	色替	無	カラーNo.	ZKS	内装色	無	無
車台No.	HB35S-102665	名義	個人	月	日	8,960円	納税済	未納税	未納税
登録No.	抹消	リサイクル	無	8,960円	納税済	未納税	未納税	未納税	未納税
定員	4人	積載量	339 kg	147 cm	153 cm	153 cm	153 cm	153 cm	153 cm
輸入車のみ	モデル	年	輸入区分	ディーラー	並行	ハンド	左	右	右
セールスポイント									
☆社外ナビゲーション☆フルセグTV☆バックカメラ☆電動格納ドアミラー☆シートヒーター☆									
ヘッドランプレイザー☆アイドリングストップ☆スマートキー☆2個☆キーレスブッシュスター									
ート									
注意事項・不具合箇所									
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入									
フロントウィンドー 飛び石									
内装 キズ、汚れ、擦れ									
室内匂い									
下廻りサビペイント									
ドアミラー キズ ヒビ フレ									
工具 無 シャッキキ 無									
mm									