

2013 MAZDA CX-5 XD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
LDA-KE2AW	2,188 cc		
YEAR / REG.	MILEAGE		
2013/03	80,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
KE2AW-114048	454 × 184 × 171 cm		
SALES POINTS			
Alloy Wheels		Cruise Control	
Navigation System			
INSPECTOR REPORT			
Rear spoiler peeling, power folding mirror faulty, age-related scratches on various parts.			

初年度登録	メーカー マツダ	ドア数 4	ボディ形状 SUV/クロカン	評価点 9																				
H25 / 3月	車名 CX-5	グレード XD	駆動区分 2WD 4WD	4																				
車種 良用途・その他()	排気量 2200 CC	型式 LDA-KE2AW	運転形式	内装 A・B・C																				
車検 - - 年 / 月 / 日	燃料 ガソリン	変速機 オートマ	後日選り貼 (保証書・取扱説明書等)																					
走行 口内にマークを記入(※交換 ※盗品 ※不審) 80,000 マイル	シフト ハイブリッド	フロア AT																						
外装色 ブラック	カラーNo. (41W)	エンジン AG・QG・WAG・()	装備品のみにO印を記入																					
()	白身車は1行に (右側)と記入	乗車定員 5人																						
ハンドル 左・右	入庫区分 ディーラー・並行	リサイクル料 11,650円 + 環境エ	Fg	Gf																				
			AM	サンルーフ																				
			AE	革シート																				
			GP	モータース																				
			DT																					
セールスポイント			 修正履 有。(B)																					
検査記入欄			<table border="1"> <thead> <tr> <th>A</th> <th>文字</th> <th>U</th> <th>ヘコキヤレ</th> <th>B</th> <th>文字・ヘコキ</th> <th>P</th> <th>熱傷・サビ</th> <th>G</th> <th>ガラスキズ</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>修繕</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </tbody> </table>		A	文字	U	ヘコキヤレ	B	文字・ヘコキ	P	熱傷・サビ	G	ガラスキズ	W	修繕	S	サビ	C	腐食	X	交換済	XX	交換済
A	文字	U	ヘコキヤレ	B	文字・ヘコキ	P	熱傷・サビ	G	ガラスキズ															
W	修繕	S	サビ	C	腐食	X	交換済	XX	交換済															
リアスボイラーハゲ 電動格納ミラー不良 各部年式不良キズ			登録地 月 日 までは各度である 車体番号 KE2AW-114048 シリアル No. 年式 備考 最大積載量																					
FW	トヨタ	備A	フレ	外装	小	ホイール	エアロ																	
					A・U	Q・曲	Q・フ																	
内装	ゴキ	シネ	ヤブレ	コグ	コグ穴	オーディオ	オーディオ																	