

2013 MAZDA CX-5 XD L Package		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE LDA-KE2FW	DISPLACEMENT 2,188 cc		
YEAR / REG. 2013/10	MILEAGE 121,760 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE SUV		
CHASSIS NO. 128238	DIMENSIONS (L X W X H) 454 × 184 × 171 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Side Camera Bose Sound System		Leather Seats Cruise Control Back Camera Navigation System	
INSPECTOR REPORT			
Left power folding mirror faulty, seat wrinkles, animal hair inside cabin, door mirror scratches, rear spoiler paint peeling.			

ORIGINAL JAPANESE AUCTION SHEET

H25/10月		メーカー マツダ		ドア数 5		ボディ形状 SUV/クロカン		評価点 4	
車名 CX-5		グレード XD Lパッケージ		駆動方式 2WD		4WD			
車種 自家用・その他 ()		排気量 2200 cc		型式 LDA-KE2FW		登録式 普通		内装 A・B・G	
燃料 ガソリン		変速機 ハンドリフト ()		シフト		後付選用品 (保証書・取扱説明書等)			
走行 121,760 km		AT							
外装色 レッド		カラーNo. 41G		エアコン AG・AC・WAG ()		新選用品のみ O印 を記入			
()		内装色		乗車定員 5人		ABS ナビ TV キーレス			
左・前・後 輸入車		ディーラー		走行 11,650 km		エアロック			
セールスポイント		ブッシュスタート、黒革シート、パワーシート、シートヒーター		修復歴 有・G		A1 AU1 AU3 A1 W2 W2 A1			
検査記入欄		左電格ミラー不良、シートしわ、ルーム内動物の毛、ドアミラーキズ、Rスポハゲ		A キズ B ハコボケサレ C キズ・ヘコミ D 色あせ・サレ E ガラスキズ F 腐食 G サビ H 変色 I 交換機 J 交換機 K 交換機 L 交換機 M 交換機 N 交換機 O 交換機 P 交換機 Q 交換機 R 交換機 S 交換機 T 交換機 U 交換機 V 交換機 W 交換機 X 交換機 Y 交換機 Z 交換機		名義中			
月 日		128238		128238		128238			
128238		128238		128238		128238			