

2013 MAZDA Flair Wagon XG		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE MM32S	DISPLACEMENT 658 cc		
YEAR / REG. 2013/06	MILEAGE 63,993 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Black		
BODY TYPE Kei			
CHASSIS NO. MM32S-102737	DIMENSIONS (L X W X H) 340 × 148 × 174 cm		
INSPECTOR REPORT			
Exterior requires repairs. Interior has some noticeable stains and dirt. No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

H25/6月	メーカー マツダ	ドア枚数 5	ボディ形状 軽四	評価点 3.5
車名 フレアワゴン	グレード XG			
車種 自家用	型式 MM32S	排気量 660	燃料 ガソリン	内装 B
車検 -年-月-日	走行 63,993 km	駆動 FWD	AC	Kg
外装色 ブラック	カラーNo. ()	リサイクル料 15,000円	車両番号 MM32S-102737	
()	シフト インパネ	AT	乗車定員 4人	長さ cm

後日送り品
(保証書・取扱説明書等)

装備
ABS・エア・AW・サドル・シート・エレクトロ・ナビ・TV・キース

セールスポイント
CD/ETC/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S/助手席エアバック/衝突安全ボディ/アイドリングストップ/ベンチシート/ミュージックブレーヤー/接続可/側面スライド
査定員記入欄

※ダメージレベルに関する注意事項
傷は記号のみ
小は1
中は2
大は3
さす 傷小 ⇒ A
へこみ 小 ⇒ U1
さす 中 ⇒ A2
さす へこみ 大 ⇒ AUB

クオリティグレード説明
外装:補修を必要とするお車です。
内装:気になる汚れ等が、部分的にあります。
修復歴:骨格部位に異常はありません。

グー鑑定 コンディションチェックシート R90126C1808
鑑定日 2025年3月18日 再鑑定日
クオリティグレード 外装 大 内装 大 修復歴 無 修復歴 無 修復歴 無 正次

車両状態の説明
小 カードサイズ未満 中 A4サイズ未満 大 A4サイズ以上 数値 全額以上

ボディ形状:軽四
エンジン:660cc
駆動:前輪駆動
変速機:AT
サスペンション:前:マクファーソン式、後:ダブルwishbone式
ブレーキ:前:ディスク、後:ドラム
タイヤ:155/70R13
ホイール:13インチ

ボディ形状:軽四
エンジン:660cc
駆動:前輪駆動
変速機:AT
サスペンション:前:マクファーソン式、後:ダブルwishbone式
ブレーキ:前:ディスク、後:ドラム
タイヤ:155/70R13
ホイール:13インチ