

2013 MITSUBISHI DELICA D:2 S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE MB15S	DISPLACEMENT 1,242 cc		
YEAR / REG. 2013/03	MILEAGE 41,000 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE Minivan			
CHASSIS NO. MB15S-206158	DIMENSIONS (L X W X H) 371 × 162 × 177 cm		
SALES POINTS			
Alloy Wheels Navigation System		Power Sliding Doors (Both Sides) (Both...	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats have scuffs and wrinkles. Exterior has minor and light scratches. Purchased with an AA rating of 4 points.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H25/3月	メーカー 三菱	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 デリカD:2 S	グレード 2WD	駆動方式 4WD	内装 A・B・C	
車種 自家用・その他()	排気量 1200 cc	型式 MB15S	選装 選装	
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 41,000 km	インパネ	AT		
外装色 グレースブルーパールメタリック	カラーNo. ()	エアコン	新着品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ	高シート	
小売 左・右 11,380円	リサイクル料	エコパック	エコ	
セールポイント CD/ウォークスルー/ETC/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ他/ワンセグTV/衝突安全ボディ/DVD再生/ミュージックプレーヤー接続可/両側電動スライドドア				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4点仕入れ				
修理歴 有 ()				
A キズ B キズ・ヘコみ C キズ・ヘコみ P 色あせ・汚れ Q ガラスキズ W 雨腐蝕 S サビ C 腐食 X 交換部 YX 交換部 売却No. 月 日 までには名義できる方 車体番号 MB15S-206158				
FW ()	機A	フレ	外装	小
内装	シシ	ヤブレ	コガ	コガ
オーディオ	オーディオ	オーディオ	オーディオ	オーディオ
長さ	幅	高さ	最大積載量	kg