

2013 MITSUBISHI Delica D5 DELICA D:5 2.0 G Power Package		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-CV2W	DISPLACEMENT 1,998 cc		
YEAR / REG. 2013/03	MILEAGE 44,439 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. CV2W-0900284	DIMENSIONS (L X W X H) 473 × 179 × 185 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Power Sliding Doors (Both Sides) (Both...	
INSPECTOR REPORT			
Exterior has minor scratches, dents, and repair marks. Interior has scuffs, stains, burns, holes, tears, rips, and a missing audio unit hole. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成25年 3月	車名・グレード デリカD5 Gパワーパッケージ	2WD 4WD	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-CV2W	排気量 2000 CC	ドア 5 形状 木
定員 7人	積載 kg	外装 C	内装 B

車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限ります)
車検 年 月 (日)	冷却 AAC	スマートキー・ETC・HJ・Dヘッドライト
走行 4万4千439 km	燃料 ガソリン	パワースライドドア (両側)
色 シルバー	色替 色コード A31U19	パドルシフト両側オートスライドドア
R券 14,710 円		装備品 (純正品に限り○をつけてください)
注意事項申告欄		(PS) (PW) (BS) (TB) (AW) SR ナビ TV カワ
外装 小A・小U		新車保証書 後日品 有・無
外装補修跡表		
ルームスレヨゴレ		
オーディオレス穴		
フロントガラス キズ・飛石・ヒビ割・リペア跡・X要		
内装 キズ・汚レ・コゲ・穴・スレ・キレ・破レ		
車台番号 0900284		
登録番号		

Top-down diagram of the vehicle showing wheel positions and labels: A1 (front), U1 (rear), W2 (side), W3 (side), T (spare), A1 (side), A1 (side), A1 (side).

A・キズ	E・エクボ	U・凹み	W・補修跡	S・サビ	C・腐食	XX・交換済
型式指定番号 17074	類別区分番号 1003	登録区分 登録	長さ 473 cm	幅 179 cm	高さ 185 cm	