

2013 MITSUBISHI Delica D5 G Power Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-CV2W	DISPLACEMENT 1,998 cc		
YEAR / REG. 2013/07	MILEAGE 142,000 km		
DOORS 5	DRIVETRAIN 2WD (FF)		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Minivan			
CHASSIS NO. CV2W-0901126	DIMENSIONS (L X W X H) 473 × 180 × 185 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Power Sliding Doors (Both Sides) (Both... Navigation System	
INSPECTOR REPORT			
Scratches present			

初年度登録		メーカー 三菱		ドア数 5		ボディ形状 ミニバン/ボックス		評価点 4	
H25 / 7月 デリカD : 5		車名		G パワーバックー ジ		駆動区分 2WD 4WD			
車種 良用途・その他()		排気量 2000 CC		型式 DBA-CV2W		通称形式		内装 A・B・C	
車検 - - 年 月 日		燃料 ガソリン		ディーゼルのシフト ハイブリッド		後日選り貼 (保証書・取扱説明書等)			
走行 口内にマークを記入(※交換 ※盗品 ※劣化) [] [] [] [] [] [] [] [] [] [] マイレージ 1 4 2 , 0 0 0 km		インパネ AT							
外装色 ホワイト		カラーNo. AG・AAO・AOG・()		装備品のみの印を記入					
()		内装色		標準定員		PS PW AW サンルーフ革シート			
ハサビと左のマークは必ず入力 (右側は任意)		ディスターン		進行方向		エアバッグ ABS ナビ TV キーレス			
		サイズタリ料		14,710円		買戻金			

セールスポイント

ユーザー買取車 / アルパイン製BIG-Xナビ / アルパイン製後席モニター / 両側電動スライド / オートクルーズコントロール / ETC車載器 / パワーシート / 3列目シート / HIDヘッドライト / オートライト

修復歴

有。(●)

A	変式	U	ヘコみ割れ	B	ガラスへこみ割れ	P	熱影響部ボロボロ	G	ガラスキズ
W	修理済	S	サビ	C	腐食	X	交換済	XX	交換済
登録地	月 日 まで(各年度異なる)								
車体番号	CV2W-0901126								

FW	トピ石	備A	フレ	外装	小 A・U	ホイール A・曲	エアロ A・フレ	シリアル No.
内装	ヨゴレ	シミ	ヤブレ	コゲ	コガケ	オーデイオ	スレ	車庫 最大積載量