

2013 MITSUBISHI Delica D5 G-Power Package		OVERALL	
		1	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-CV5W	DISPLACEMENT 2,359 cc		
YEAR / REG. 2013/01	MILEAGE 106,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. CV5W-0801487	DIMENSIONS (L X W X H) 473 × 180 × 187 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Sliding Doors (Both Sides) (Both... Back Camera Rear Seat Entertainment (Rear seat 9-in...	
INSPECTOR REPORT			
Exterior needs repair. Interior has some noticeable stains. No frame damage.			

ORIGINAL JAPANESE AUCTION SHEET

青森県内のカー販売/AAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H25/1月	メーカー 三菱	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 1			
車名 デリカD:5	グレード G-Power package	DBA-CV5W	2400	ガソリン	B		
車種 自家用	形式 右	走行 106,000	マイル 000	4WD	AC	Kg	
カラーNo. 90-501710-1	リサイクル料 14,710円	販売店 CV5W-0801487	シフト AT	乗車定員 7人	長さ cm	幅 cm	高さ cm
備付品 (保証書・取扱説明書等)	ディーラー保証書 2013年5月18日						
装備 ①②③④⑤⑥⑦⑧⑨⑩⑪⑫⑬⑭⑮⑯⑰⑱⑲⑳㉑㉒㉓㉔㉕㉖㉗㉘㉙㉚㉛㉜㉝㉞㉟㊱㊲㊳㊴㊵㊶㊷㊸㊹㊺㊻㊼㊽㊾㊿	車両状態の診断 小 中 大 大以上						
セールスポイント 3列シートにDVDバックカメラ/TC/ナビ/Bluetooth/スマートキー/キーレスエントリー/ABS/ESP/エアバッグ/サイドエアバッグ/フルセグ/V/衝突被害軽減ブレーキ/衝突安全ボディ/AWD/オートクルーズコントロール/VD再生/ミュージックサーバー/パナソニックブルーレイ/液晶ナビ/モニター/両側電動スライドドア/認定中古車	車両状態の診断 小 中 大 大以上						
※ダメージレベルに関する注意事項 最小は0点のみ 0点以上 1点以上 2点以上 3点以上	車両状態の診断 小 中 大 大以上						
外装 ボディカラー パールホワイト	車両状態の診断 小 中 大 大以上						
内装 シートカラー ブラック	車両状態の診断 小 中 大 大以上						
クオリティグレード説明 外装:補修を必要とする車です。 内装:気になる汚れ等があります。 修復部:骨格部に異常はありません。	車両状態の診断 小 中 大 大以上						