

2013 Nissan CIMA Hybrid		OVERALL	3.5
		EXTERIOR	INTERIOR
MODEL CODE		DISPLACEMENT	
DAA-HGY51		3,498 cc	
YEAR / REG.		MILEAGE	
2013/07		117,534 km	
DOORS		SEATS	
4		5	
DRIVETRAIN		TRANSMISSION	
2WD (FR)		AT	
FUEL		STEERING	
Hybrid (Petrol)		Right	
EXTERIOR COLOR		BODY TYPE	
Silver		Other	
CHASSIS NO.		DIMENSIONS (L X W X H)	
HGY51-602547		512 × 185 × 151 cm	
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats		Power Seats (Front)	
Pre-Collision Braking		Adaptive Cruise Control	
Side Camera		Back Camera	
Navigation System		Bose Sound System (10 speakers)	
INSPECTOR REPORT			
Front windshield has stone chips and underbody rust. The interior shows wear, scratches, scuffs, and dirt on soft knobs, trim, driver's door interior, passenger seat, passenger door interior, dashboard, and rear seat surface. The driver's door interior also has cuts and screw holes, and the passenger seat has minor wrinkles.			

[illegible]