

2013 Nissan March 5HB S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE K13	DISPLACEMENT 1,198 cc		
YEAR / REG. 2013/06	MILEAGE 37,217 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. K13-043345	DIMENSIONS (L X W X H) 383 × 167 × 152 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present. Repair history: No abnormalities in the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H25/6月	メーカー 日産	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 マーチ	グレード S			
車種 自家用	右	型式 K13	総排気量 1200	燃料 ガソリン
年 -	月 -	日 -	走行 37,217 km	変速機 AC
カラーNo. ホワイトパール	リサイクル料 8,350円	車両番号 K13-043345	長さ cm	高さ cm
シフト フロア	AT	定員 5人	幅 cm	全高 cm

後日送り品
(保証書・取扱説明書等)

装備
CD/ETC/運転席エアバック/キーレスエントリー/ABS/助手席エアバック/メモリーナビ他/フルセグTV/衝突安全ボディ

査定員記入欄

※ダメージレベルに関する注意事項
傷は記号のみ
小傷: 1
中傷: 2
大傷: 3
※ 1: 全長 1/3 以下
※ 2: 全長 1/3 以上 1/2 以下
※ 3: 全長 1/2 以上

ボディ
外装
内装
エンジン
変速機
ブレーキ
サスペンション
タイヤ
ホイール
その他

クオリティグレード説明
外装: 気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。
内装: 気になる汚れ等が、部分的にあります。
修復歴: 骨格部位に異常はありません。

車両状態の補綴は、停止状態で実施できる範囲で行っています。