

2013 Subaru XV 2.0i-L EyeSight 4WD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-GP7	1,995 cc		
YEAR / REG.	MILEAGE		
2013/07	52,900 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GP7-049306	445 × 178 × 160 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System			
INSPECTOR REPORT			
Light scratches on the exterior.			

初年度登録	メーカー	ドア数	ボディ形状	年式	SUV/クロカン	評価点																				
H25 / 7月	スバル	5	2.0 i-L アイサ イト 4WD	グレード	2WD 4WD	3.5																				
車種	自家用・その他 ()	排気量	型式	国産	内装	A・B・C																				
車検	2000 CC	DBA-GP7	燃費	燃費	燃費	燃費																				
走行	52,900 km	フロア AT	燃料	ディーゼル	日産	日産																				
外装色	ブラック (D4S)	エンジン	AD・600・WAG・()	装備品のみ O印 を記入	サドル	革シート																				
内装色	黒革	5人	5人	エレクトロ	エレクトロ	エレクトロ																				
左・右	ディーラー	走行	12,030円	エレクトロ	エレクトロ	エレクトロ																				
セールスポイント																										
検査記入欄	<table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘッドライト</td> <td>B</td> <td>キズ/ヘッドライト</td> <td>P</td> <td>熱影響/サビ</td> <td>G</td> <td>ガラス/キズ</td> </tr> <tr> <td>W</td> <td>燃料タンク</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </table>						A	キズ	U	ヘッドライト	B	キズ/ヘッドライト	P	熱影響/サビ	G	ガラス/キズ	W	燃料タンク	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘッドライト	B	キズ/ヘッドライト	P	熱影響/サビ	G	ガラス/キズ																	
W	燃料タンク	S	サビ	C	腐食	X	交換済	XX	交換済																	
外装薄い線キズ	<table border="1"> <tr> <td>登録年</td> <td>月</td> <td>日</td> <td>家まで名義がある</td> </tr> <tr> <td>車体番号</td> <td colspan="3">GP7-049306</td> </tr> </table>						登録年	月	日	家まで名義がある	車体番号	GP7-049306														
登録年	月	日	家まで名義がある																							
車体番号	GP7-049306																									
FW	トビ石	備A	フレ	外装	小	ホイル	エアロ																			
内装	ヨゴレ	シミ	ヤブレ	コグ	コグス	オーデイオ	スレ																			