

2013 Suzuki Jimny Cross Adventure		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE JB23W	DISPLACEMENT 658 cc		
YEAR / REG. 2013/01	MILEAGE 85,160 km		
DOORS 3	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Kei		
CHASSIS NO. JB23W-690750	DIMENSIONS (L X W X H) 340 × 148 × 168 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but small scratches and dents remain. Interior: Some noticeable stains are present in parts. Repair history: No abnormalities in the frame.			

車種内でのグレード・色・JAA/A鑑定証の写りと下記記載の評価は異なります									
初年度登録 H25 1月		メーカー スズキ		ドア枚数 3		ボディ形状 軽四		評価点 4.5	
車名 ジムニー		グレード クロスアドベンチャー							
車種 自家用		型式 J B23W		排気量 660		燃料 ガソリン		内装 B	
車検 8 1 年 月 / 抹消		走行 85 16 0 km		駆動 4WD		変速機 AC		安全装置 K	
外装色 パール		カラー-No. ()		リサイクル料 9,010円		車台番号 J B23W-690750			
() ()		シフト フロア 4 AT		乗車定員 4人		長さ cm		高さ cm	
後日送り状 (保証書 ・ 取扱説明書 等) 車検 PG ☒ EV ☒ セルフ ☒ シート ☒ ウインド ☒ ドア ☒ TV ☒ ガラス ☒									
セールスポイント									
CDバックカメラ/運転席エアバック/キーレスエントリー/A B S /助/手動エアバック/モリーナビ/ワンスゲTV/衝突安全ボディHWD/スタートヒーター/D V 両生									
査定員記入欄									
※ダメージレベルに関する注意事項 傷は記載の必須 小傷? 必ず 傷小 ⇒ A 中傷? 必ず 傷中 ⇒ B 大傷? 必ず 傷大 ⇒ C 必ず 傷中 ⇒ B 必ず 傷大 ⇒ C									
W H D L F L A L E L W H D L F L A L E L									
W H D L F L A L E L W H D L F L A L E L									

W H D L F L A L E L W H D L F L A L E L									
W H D L F L A L E L W H D L F L A L E L									
W H D L F L </									