

2013 Suzuki Solio Bandit Solio 1.2 Bandit		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-MA15S	DISPLACEMENT 1,242 cc		
YEAR / REG. 2013/07	MILEAGE 48,675 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Hatchback		
CHASSIS NO. MA15S-659424	DIMENSIONS (L X W X H) 371 × 162 × 176 cm		
SALES POINTS			
Alloy Wheels Navigation System		Power Sliding Doors (Both Sides) (Both...	
INSPECTOR REPORT			
Exterior: Minor scratches (A), minor dents (U). Door mirror scratches. Seat scuffs. Front glass: Scratches, stone chips, cracks, repair marks, replacement recommended. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成25年 7月	車名・グレード ソリオバンディット バンディット	2WD 4WD	評価点 (4)
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-MA15S	排気量 1200 CC	ドア 5 形状 木 定員 5人 積載 kg
車種 自家用	シフト CAT	セールスポイント (正常に機能するものに限ります)	
車検 年 月 (日)	冷却 AAC	スマートキー・社外アルミホイール・ETC	
走行 4万8千675 km	燃料 ガソリン	HIDヘッドライト・パワースライドドア (両側)	
色 ブラウン	色替 ZED	両側Aスライド・ETC・HID・ドラレコ	
R券 10,800 円		装備品 (純正品に限り○をつけてください)	
注意事項申告欄		(PS) (PW) (BS) (AB) (AW) SR ナビ TV カワ	
外装 小A・小U		新車保証書 後日品 有・無	
ドアミラー キズ			
シート すれ			
フロントガラス キズ・ひび割れ・リペア跡・X要			
内装 キズ・汚レ・コゲ・穴・ズレ		A-キズ E-エクボ U-ひび W-補修跡 S-サビ C-腐食 XX-交換済	
車台番号 659424		型式認定番号 16746	類別区分番号 0018
登録番号		全長 371 cm	全幅 162 cm