

2013 Suzuki WagonR 660 FX		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-MH34S	DISPLACEMENT 658 cc		
YEAR / REG. 2013/06	MILEAGE 93,500 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. MH34S-200605	DIMENSIONS (L X W X H) 340 × 148 × 164 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Exterior A, luggage compartment A, interior A with dirt, wheel covers A, left door mirror A-A, seat dirt, puncture repair kit included.			

ORIGINAL JAPANESE AUCTION SHEET

H25 / 6月		メーカー スズキ		ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4																				
車名 ワゴン R		グレード 660 FX		駆動方式 4WD																						
車種 自家用・その他(レンタカー)	排気量 660 CC	型式 DBA-MH34S	通称 型式	内装 A・B・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	検日通り品 (盗難・取替印等)																							
走行 93,500 km	シフト ハイブリッド	インパネ	CVT																							
外装色 スベリアホワイト	カラーNo.	エアコン	AG・AG・WAG・	装備品のみ ORP を記入																						
()	内装色	乗車定員	4 人	PS	PS	AW																				
左・右	ディーラー	走行	8,930 円	エアバック	ABS	ETC																				
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/メモリーナビ他(カロッツェリア・AVIC-MR Z03)/ワンセグTV/ワンオーナー/ETC/アイドリングストップ/盗難防止システム/ベンチシート/フルフラット/CD/バックカメラ/定期点検記録簿																										
検査記入欄 外装A/荷物室A/内装A汚れ/ホイールカバーA/左ドアミラーA/シート汚れ/バンク修理KIT有																										
検査結果 <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>腐蝕跡</td><td>S</td><td>サビ</td><td>C</td><td>変色</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table> 登録No. _____ 月 _____ 日 _____ までにも名実できる方 車体番号 MH34S-200605 シリアル No. _____ 内装 300 シス ヤブレ コガ コガ穴 オーディオ穴 40 長さ 幅 高さ 最大積重量 Kg							A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ	W	腐蝕跡	S	サビ	C	変色	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ																	
W	腐蝕跡	S	サビ	C	変色	X	交換済	XX	交換済																	