


2013 Toyota MarkX 2.5 Premium		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GRX130	DISPLACEMENT 2,499 cc		
YEAR / REG. 2013/05	MILEAGE 55,936 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. GRX130-6072470	DIMENSIONS (L X W X H) 475 × 179 × 143 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Seats (Front) Back Camera	
INSPECTOR REPORT			
Exterior has minor scratches (A) and dents (U). Right C-pillar has a dent. Rear bumper is misaligned. Seats and steering wheel are misaligned. Interior is dirty. Left rear power window is faulty. Front windshield has scratches, stone chips, cracks, and repair marks, requiring replacement. Interior has scratches, dirt, burn marks, holes, scuffs, and tears.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成25年 5月		車名・グレード マークX プレミアム		2WD 4WD		評価点 (4)	
ディーラー・並行 型式		DBA-GRX130		排気量 2500	ドア 4	定員 5人	外装 内装 B B
モデル年式 年		DBA-GRX130		燃料 ガソリン	形状 SD	積載 kg	
ハンドル 左・右							
車種 自家用		シフト FAT		セールスポイント (正常に機能するものに限りです)			
車検 年 月 (日)		冷房 AAC		スマートキー・ETC・HIDヘッドライト			
走行 5万5千 936 km		燃料 ガソリン		純正メモリーナビ バックカメラ ETC			
色 パール		色コード 062/FC20		諸備品 (純正品に限り○をつけてください)			
R券 12,580 円				(PS) (PW) (BS) (AB) (AW) SR ナビ TV カワ			
注意事項申告欄				新車保証書 後日品 有・無			
外装 小A・小U 右CピラーU Rバンパーずれ シート すれ ハンドル すれ 室内 汚れ 左R席 不良							
フロントガラス キズ・傷・ヒビ割・リペア跡・X要		内装 キズ・傷・コゲ・穴・破・キレ・破レ		A-キズ E-エウボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済 型式検査番号 16360 車検区番号 0009 登録年月 475 長さ 179 高さ 143			
車台番号 6072470							
登録番号							