

2013 Toyota MarkX 250G		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GRX130	DISPLACEMENT 2,499 cc		
YEAR / REG. 2013/07	MILEAGE 75,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. GRX130-6077318	DIMENSIONS (L X W X H) 475 × 180 × 144 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
Navigation System			
INSPECTOR REPORT			
Exterior has some noticeable scratches and dents. Interior has some noticeable stains in parts. No abnormalities in the frame.			

青竹内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります																																																	
初年登録簿 H25 7月	メーカー トヨタ 車名 マークX	ドア枚数 4 グレード 250G	ボディ形状 セダン	評価点 3																																													
用途 自家用	型式 右	DBA-GRX130	排気量 2500	燃料 ガソリン																																													
年式 - - 年 - - 月 - - 日	走行距離 75,000 km	C/Dマークを記入(※：●=新車、☆=中古) 色別 白	燃費 AC	備考欄																																													
カラーNo. シムラ・メテリカ	リサイクル料 12,580円	車両番号 GRX130-6077318	長さ cm	幅 cm																																													
()	内装 AT	シート フロア	高さ cm	重量 kg																																													
旅行口送り (保証書・取扱説明書等)																																																	
装備																																																	
☒ ABS	☒ VSC	☒ サルベージメント	☒ レット																																														
☒ ナビゲーション	☒ パンク	☒ BGS	☒ TV	☒ XLS																																													
セールスポイント																																																	
パワースーツードアクカメラETC/機内防犯装置(E.S.C)/HID・キセノン・ディスプレイナビ搭載エアバック座席制動システム/スマートキー/キーレスエントリー(AES)両方搭載エアバックサイドイミュレーション/VTD/再生/ミュージックプレイヤー接続可																																																	
検定書記入欄																																																	
※所ダメージレベルに関する注意事項 軽小は記号のみの場合、必ず「軽小」＝A 軽中＝B 軽大＝C 軽特大＝D ※必ず「軽小」＝A ※必ず「軽中」＝B ※必ず「軽大」＝C ※必ず「軽特大」＝D <table border="1" style="width: 100%; font-size: small;"> <thead> <tr> <th>F</th> <th>V</th> <th>B</th> <th>M</th> <th>L</th> <th>R</th> <th>S</th> <th>A</th> <th>P</th> <th>E</th> <th>T</th> <th>O</th> <th>N</th> <th>I</th> <th>D</th> <th>A</th> <th>R</th> <th>L</th> <th>A</th> <th>F</th> <th>L</th> <th>E</th> <th></th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> クロスリフトグレード説明 外装: 横になるようなズバリやヘコミがある。 内装: 横になる汚れ等が、部分的にあります。 修復部: 骨格部位に異常はありません  写真裏面の確認は、写真状態で実施できる範囲で行います。					F	V	B	M	L	R	S	A	P	E	T	O	N	I	D	A	R	L	A	F	L	E																							
F	V	B	M	L	R	S	A	P	E	T	O	N	I	D	A	R	L	A	F	L	E																												