

2013 Toyota Passo X Kutlogi		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE KGC30	DISPLACEMENT 996 cc		
YEAR / REG. 2013/02	MILEAGE 64,900 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Brown	BODY TYPE Hatchback		
CHASSIS NO. KGC30-0140162	DIMENSIONS (L X W X H) 364 × 167 × 154 cm		
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small ones remain. Interior: Some noticeable stains and dirt are present in parts. No abnormalities in the structural components.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なりです

初年度登録 H25/2月	メーカー トヨタ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 パッソ	グレード X	クツロギ		
車種 自家用	型式 KGC30	排気量 1000	燃料 ガソリン	内装 B
車検 8年2月/抹消	走行 64,900 km	マイル 100	駆動 AC	最大積載量 Kg
外装色 ダークレッドマイカ	カラーNo. ()	リサイクル料 8,790円	販売店 KGC30-0140162	
()	シフト コラム	AT	乗車定員 5人	長さ cm
後日送り品 (保証書・取扱説明書等)	車高状態の確認は、停止状態で実施できる範囲で行っています。走行状態は走行中チェックを行うものではございません。もしシートベルトの着用や乗降時などを行う場合は、必ず運転席に乗り込んで確認をお願いします。			

装備
④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿

セールスポイント
CD/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/衝突安全ボディ
査定員記入欄

※ダメージレベルに関する注意事項
傷は記号のみ
小は1
中は2
大は3
さす 傷小 ⇒ A
へこみ 小 ⇒ U1
さす 中 ⇒ A2
さす へこみ 大 ⇒ A3

ボディ
F W ト 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

内装
F W ト 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

クオリティグレード説明
外装: 気になるキズやへこみは補修済みですが、小さなキズやへこみが残っています。
内装: 気になる汚れ等が、部分的にあります。
修復歴: 骨格部位に異常はありません。

車両状態の確認は、停止状態で実施できる範囲で行っています。