

2013 Toyota Pixis Epoch X		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-LA300A	DISPLACEMENT 658 cc		
YEAR / REG. 2013/05	MILEAGE 49,411 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Kei		
CHASSIS NO. LA300A-1010116	DIMENSIONS (L X W X H) 340 × 148 × 149 cm		
INSPECTOR REPORT			
Right panel dent, seat wear/sagging, steering wheel wear, door mirror scratches, wheel cap scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25		メーカー トヨタ		ドア枚数 5		ボディ形状 軽四		評価点 3.5																					
5月		車名 ピクシスエポック X		グレード		駆動区分 2WD 4WD																							
車歴 自用・その他 ()	排気量 660	型式 DBA-LA300A	通称 型式	内装 A・B・C																									
車検 10年5月 / 抹消	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書等)																										
走行 49,411マイル	シフト ハイブリッド	AT																											
外装色 クロ	カラーNo. X07	エアコン	新備品のみ O印 を記入																										
()	色変更はO印に 「色変」と記入	内装色	乗車定員 4人	PS	PA	AW	サンルーフ	革シート																					
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料	7,320円	預託料	エエ/バック	ABS	ナビ																				
セーレスポイント																													
検査記入欄				修復歴 有 ()																									
R/パネルヒズミ、シートスレヘタリ、ハンドルスレ、ドアミラーキズ、ホイールCPキズ				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ・凹み</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・剥落</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>						A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																				
登録No.				名義中																									
月 日				までに名義できる方																									
車体 番号				LA300A-1010116																									
シリアル No.																													
PW	トド石	ワレ	外装	小	ホイール	エアロ																							
内装	ヨコ	シミ	ヤブレ	コゲ	コゲ穴	オーディ穴	スレ	長さ	幅																				
							高さ	最大積載量	Kg																				