

2013 Toyota Prius a 1.8S		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DAA-ZVW41W	1,797 cc		
YEAR / REG.	MILEAGE		
2013/04	142,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Gray	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZVW41-3253177	462 × 178 × 158 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
INSPECTOR REPORT			
Roof spoiler faded, rear bumper near center has scratches and dents, seat faded.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/4月	メーカー トヨタ	ドア枚数 5	ボディ構造 ミニバン/ワンボックス	評価点 3
車名 プリウスα	グレード 1.8Sナビバックカメラ付 ETC	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 1800 cc	型式 DAA-ZVW41W	運転形式	内装 A・⑨・C
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)	
走行 142,000 km	シフト インパネ	CVT		
外装色 グレーメタリック	カラーNo. ()	エアコン	新着品のみ O印 を記入	
内装色 ()	乗車定員 5 人	PS	サンルーフ	革シート
ハンドル 左・()	輸入 区分	ディーラー	走行 13,120 円	エアロ
セールスポイント		P2 AU2		
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/アイドリングストップ/スマートキー/盗難防止システム/横滑り防止装置 (E S C)		修復歴 有・⑨		
検査記入欄		A キズ U ヘビイサレ B キズ・ヘビサ C 色あせ・サケ G ガラスキズ		
ルーフスポイラー色褪せ。リヤバンパー中央付近傷、凹み。シート色褪せ。		W 補修跡 S サビ C 腐食 X 交換席 XX 交換席		
確認事項等ありましたらお問合せください。		登録No. 月 日 までに名変更できる方		
		名変更		
		車検番号 ZVW41-3253177		
FW トビ石 傷A フレ 外装 小	ホイール エアロ	シリアル No.		
内装 ヨゴレ シミ ヤブレ コゲ	コゲ穴 オーディオ穴 スレ	長さ cm	幅 cm	高さ cm
		最大積重量 Kg		