

2013 Toyota Prius S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ZVW30	DISPLACEMENT 1,797 cc		
YEAR / REG. 2013/04	MILEAGE 45,593 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. ZVW30-5634999	DIMENSIONS (L X W X H) 448 × 175 × 149 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: There are noticeable scratches and dents. Interior: There are some noticeable stains in parts. Repair History: No abnormalities in the structural components.			

青神市内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は真なります					
初年登録 H25 4月	メーカー トヨタ	ドア枚数 5	ボディ形状 セダン	評価点 4	
車名 プリウス		グレード S			
用途 自家用	形式 右置式	型式 ZVW30	防犯 1800	燃料 ハイブリッド	内装 B
年 - - 年 - - 月 - - 日		CPOCマークを記入(※:交番・S:盗犯・P:マフラー) CPOC 1 4 5 9 3		車庫番号 ZVW30-5634999	
カラーNo. ()		リサイクル料 11,820円		重量 1800	
シフト インパネ AT		乗車定員 5人	長さ cm	幅 cm	高さ cm
旅行送り (保証書・取扱説明書等)					
装備 ◎ AV ○ V オイル センター シート ナビゲーション パワーステアリング セールスポイント					
C/DバックカメラETC横滑り防止装置 (ESC)(HID・ゼロノン・ディス チャージ)運転席エアバック/後座席シス テム(スマートキー/パーソナルエントリー/A BS/電子駐車エアバックサイドエアバ ム/メモリーナビゲーションセグT/衝突安全ボ ディー 常定乗記入欄					
※ダメージレベルに関する注意事項 最小は0年のもの 小傷1 中傷2 大傷3 例: 小傷1 = A 中傷2 = B 大傷3 = C					
F フロント	R リア	L 左側	R 右側	A 前面	B 後面
F フロント	R リア	L 左側	R 右側	A 前面	B 後面
クオリティグレード説明 外装: 傷になるようなキズやヘコミ があります。 内装: 傷になる汚れ等が、部分的に あります。 修繕歴: 骨格部位に異常はありません					

車体写真撮影確認済、正常状態で実車で検査を実施して行っています。