


2013 Toyota Prius S		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ZVW30	1,797 cc		
YEAR / REG.	MILEAGE		
2013/08	69,072 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Purple	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZVW30-5676572	448 × 175 × 149 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Right front instrument panel bodywork/paint, left center pillar dent			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/8月	メーカー トヨタ	ドア枚数 5	ボディ形状 セダン	評価点 R																				
車種 プリウス	グレード S	駆動区分 2WD 4WD																						
車体 自家用・その他 ()	排気量 1800 cc	型式 ZVW30	通称 A・C	内装 A・C																				
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ハイブリッド	後日送り品 (保証書・取扱説明書等)																					
走行 69,072 km	シフト フロア	AT																						
外装色 ライトパープルマイカメタリック	カラーNo. ()	エアコン ()	新着品のみ O印 を記入																					
内装色 ()	乗車定員 5人	PS	サンルーフ	革シート																				
左・右 左・右	輸入 ディーラー	走行 11,820 km	エアロ	ABS																				
セールスポイント CD/バックカメラ/TC/横滑り防止装置 (ESC) /HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/フルセグTV/衝突安全ボディ/アイドリングストップ/DVD再生																								
検査記入欄 右FインパネBP 左センターピラー凹み																								
																								
修復歴 ○ 無																								
<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>					A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録No. 月 日 までに名義できる方																								
車検番号 ZVW30-5676572																								
シリアル No.																								
長さ cm 幅 cm 高さ cm 最大積重量 kg																								