

2013 SUBARU XV 2.0i-L EyeSight		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GP7	DISPLACEMENT 1,995 cc		
YEAR / REG. 2013/05	MILEAGE 56,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. GP7-041786	DIMENSIONS (L X W X H) 445 × 178 × 160 cm		
SALES POINTS			
Alloy Wheels Navigation System		Adaptive Cruise Control	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, minor exterior scratches and light scratches. Purchased with an AA 4-point rating. Minor scratch on the bottom of the bumper.			

ORIGINAL JAPANESE AUCTION SHEET

車種 H25/5月	メーカー スバル	ドア枚数 5	ボディタイプ SUV/クロカン	評価点 4
車名 XV	グレード 2.0i-L	駆動方式 2WD	燃費区分 4WD	
車検 -	年 -	月 -	日 -	
走行 56,000	マイル 91,340	フロア	AT	
外装色 デザートカーキ	カラーNo. A	エンジン 2.0i-L	変速機 AT	
内装色 ブラック	カラーNo. A	乗車定員 5人	オプション サンルーフ	
小売価格 12,030円	登録料 12,030円	消費税 1,203円	車体番号 GP7-041786	
セールスポイント パワーシート/CD/バックカメラ/TC/横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ/運転席 エアバック/盗難防止システム/スマートキー/キーレスエ ントリー/ABS/助手席エアバック/HDDナビ/フルセグ TV/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイ ドリングストップ/DVD再生				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価4点仕入れ バンパー下A				
修理履歴 有・無 A キズ U ヘッドライト B キズ・ヘッドライト C 色あせ・ボケ D ガラス割 W 雨漏り S サビ C 腐食 X 交換 Y 交換 Z 交換 車検No. 月 日 まで有効 車体番号 GP7-041786				
FW	トランス	エンジン	変速機	駆動方式
内装	シート	ドア	窓	ガラス