

2014 Audi Audi A3 Sedan 1.8 TFSI Quattro		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ABA-8VCJSL	1,798 cc		
YEAR / REG.	MILEAGE		
2014/12	78,459 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WAUZZZ8V6E1023900	447 × 180 × 139 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Steering wheel wear, driver's seat tear, seat stains, studless tires.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 12月	メーカー アウディ	ドア枚数 4	ボディ形状 セダン	評価点 4
車名 A 3 セダン	グレード 1.8TFSIクワトロ	駆動区分 2WD 4WD		
車種 自家用 ・ その他 ()	排気量 1800 cc	型式 ABA-8VCJSL	通称 型式	内装 A ・ B ・ C
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送り品 () 保証書 ・ 取扱説明書 等 ()	
走行 78,459 km	シフト AT			
外装色 ホワイト	カラーNo. ()	エアコン AG ・ QG ・ WAG ・ ()	新着品のみ O印 を記入	
内装色 ()	乗車定員 5 人	サンルーフ	革シート	
ハンドル 左 ・ 右	輸入 区分	走行 15,470 km	エアバック	ABS
セールスポイント コンビニエンスパッケージ、リアビューカメラ、HID ヘッドライト、純正ナビ、地デジ、4WD、オートエアコ ン		修復歴 有 ()		
検査記入欄 ハンドルハゲ、Dシート破れ、シートシミ、スタッドレ スT		A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ G ガラスズ W 補修部 S サビ C 腐食 X 交換部 XX 交換所 登録No. 月 日 までに名変できる方 名変中 車検 番号 WAUZZZ8V6E1023900		
FW (トビ) ()	ワレ	外装 小 () ・ ()	内装 A ・ フレ	シリアル No.
内装 ()	シミ	ヤブレ	コガ	コガ穴
オーディオ穴		最大積載量 kg		