

2014 BMW 2 SERIES M235i Coupe Black Leather Navigation Backup Camera Corner Sensor		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-1J30	DISPLACEMENT 2,979 cc		
YEAR / REG. 2014/03	MILEAGE 26,130 km		
DOORS 2	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Coupe		
CHASSIS NO. WBA1J72020VX83622	DIMENSIONS (L X W X H) 447 × 177 × 141 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Cruise Control		Leather Seats Pre-Collision Braking Navigation System	
INSPECTOR REPORT			

前期登録 H26 / 3月		デカー BMW		ドア枚数 2		ボディ形状 クーペ		評価点 4.5	
車種 自動車・その他 ()		排気量 2970 CC		型式 DBA-1J 30		連検 12月		内装 A・B・C	
車検 9年3月		抹消 燃料 無鉛ハイブリッド ()		ディーゼル ()		検日通り品 () 色差・取付印等 ()			
走行 口内にマップを記入(※交換 ※送付 ※受領)		シフト フロア AT		スピーカー有り					
外装色 ブラック		カラーNo. ()		エアコン AG・AGG・WAG・()		装飾品のみ O印 を記入			
()		色変更は1回に1色限りと記入		内装色 ()		乗車定員 4人		(F) (P) (AV) サンプル 取付ト	
パン 左・右		輸入 部分		ナイザクリ料 18,110円・取付工		エアック (F) (P) (AV) (TV) (モ)		(F) (P) (AV) サンプル 取付ト	
セールスポイント									
検査記入欄				修復歴 有・無					
FW トビ石 傷A フレ 外装 小 曲 A・ウレ エアロ シリアル No.				A キズ U ヘッドライト B キズ(ヘッド) C 色あせ・ボケ G ガラスキズ W 傷跡 S サビ C 腐食 X 交換部 XX 交換済					
名義				月 日 までに各處で受ける					
車体番号 WBA1J 72020VX 83622				最大積重量					
FW トビ石 傷A フレ 外装 小 曲 A・ウレ エアロ シリアル No.				最大積重量					