


2014 BMW 3series Touring 320d Touring		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-3D20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2014/09	MILEAGE 99,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Station Wagon		
CHASSIS NO. WBA3K32040F792637	DIMENSIONS (L X W X H) 463 × 180 × 146 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Pre-Collision Braking Back Camera		Roof Rails Power Seats (Front) Cruise Control Navigation System	
INSPECTOR REPORT			

初年度登録		メーカー		ドア数		ボディ形状		評価点																																																															
H26 / 9月		BMW		5		ステーションワゴン		9																																																															
車名		3シリーズ		グレード		320d ツーリン		車種区分 2WD 4WD																																																															
車種		自家用・その他 ()		排気量 2000 CC		型式 LDA-3D20		内装 A・⑨・C																																																															
車検		9年10月 / 扶消		総割 ガソリン ハイブリッド ()		後付選付品 (保証書・取扱説明書等)																																																																	
走行		99,000 km		シフト フロア AT																																																																			
外装色		カラーNo. 300		エンジン AG・BG・WAG・()		装備品のみ O印 を記入																																																																	
()		内装色		標準車種		PS PW AW サンルーフ 革シート																																																																	
左・(車)		輸入 区分		走行		PS PW AW サンルーフ 革シート																																																																	
登録		400,000円		5年保証		ABS ナビ TV キーレス																																																																	
セールポイント																																																																							
検査記入欄																																																																							
備考		 修復歴 有・()																																																																					
検査結果		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ</td> <td>サビ</td> <td>B</td> <td>キズ</td> <td>H</td> <td>20</td> <td>色あせ</td> <td>ベテ</td> <td>G</td> <td>ガラス</td> </tr> <tr> <td>W</td> <td>補修部</td> <td>S</td> <td>サビ</td> <td>C</td> <td>調査</td> <td>X</td> <td>交換</td> <td>XX</td> <td>交換</td> <td>XX</td> <td>交換</td> <td>交換</td> </tr> <tr> <td colspan="12">登録No.</td> </tr> <tr> <td colspan="12">月 日 までに名義変更する</td> </tr> <tr> <td colspan="12">車検番号 WBA3K32040F 792637</td> </tr> </table>								A	キズ	U	へこみ	サビ	B	キズ	H	20	色あせ	ベテ	G	ガラス	W	補修部	S	サビ	C	調査	X	交換	XX	交換	XX	交換	交換	登録No.												月 日 までに名義変更する												車検番号 WBA3K32040F 792637											
A	キズ	U	へこみ	サビ	B	キズ	H	20	色あせ	ベテ	G	ガラス																																																											
W	補修部	S	サビ	C	調査	X	交換	XX	交換	XX	交換	交換																																																											
登録No.																																																																							
月 日 までに名義変更する																																																																							
車検番号 WBA3K32040F 792637																																																																							
車検		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>PW</td> <td>トビ石</td> <td>傷A</td> <td>フレ</td> <td>外装</td> <td>小</td> <td>ホイール</td> <td>エアロ</td> </tr> <tr> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2">A・U</td> <td>A・曲</td> <td>A・フレ</td> </tr> <tr> <td>内装</td> <td>正割</td> <td>シシ</td> <td>ヤブレ</td> <td>コガ</td> <td>コガ</td> <td>オー</td> <td>スレ</td> </tr> <tr> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2">A・U</td> <td>A・曲</td> <td>A・フレ</td> </tr> </table>								PW	トビ石	傷A	フレ	外装	小	ホイール	エアロ					A・U		A・曲	A・フレ	内装	正割	シシ	ヤブレ	コガ	コガ	オー	スレ					A・U		A・曲	A・フレ																														
PW	トビ石	傷A	フレ	外装	小	ホイール	エアロ																																																																
				A・U		A・曲	A・フレ																																																																
内装	正割	シシ	ヤブレ	コガ	コガ	オー	スレ																																																																
				A・U		A・曲	A・フレ																																																																