

2014 BMW X4 xDrive 35i M Sport		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE XW35	DISPLACEMENT 2,979 cc		
YEAR / REG. 2014/12	MILEAGE 9,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. WBAXW520900F89931	DIMENSIONS (L X W X H) 468 × 190 × 163 cm		
SALES POINTS			
Alloy Wheels Roof Rails Power Tailgate Pre-Collision Braking Front Camera Back Camera		Sunroof Leather Seats (Leather) Power Seats (Front) Cruise Control Side Camera Navigation System	
INSPECTOR REPORT			
Small scratch on mirror A, medium wrinkles on seats, medium scuff on steering wheel, repair marks on left rear door, headlight lens deterioration.			

ORIGINAL JAPANESE AUCTION SHEET

H26 / 12月		BMW		5		SUV/クロカン		4	
X 4		xDrive 35i Mスポーツ		2WD		4WD			
車種 自家用・その他 ()		排気量 3000 cc		型式 XW35		登録区分 A・⑤・C			
年 月 日		燃料 ディーゼル		後付選用品 (保証書・取扱説明書等)					
走行 9,000 km		フロア 8 AT							
外装色 ブラックサファイア		カラーNo.		新車登録 ()					
()		内装色		5人					
左・前・後・右		22,240円		22,240円					
セールスポイント 本革シート/パワーシート/CD/DVDバックカメラ/ETC横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/ターボシートヒーター/電動リアゲート/DVD再生/ミュージックサーバー/ミュージックプレイヤー接続可/全周カメラ/フロントカメラ/サイドカメラ									
検査記入欄 ミラーA (小) シートレハ (中) ハンドルすれ (中) 左後ドア修理跡 ヘッドライトレンズ劣化									
修復歴 有・⑥									
名義中 月 日 まで 名義で売却									
車体番号 WBAXW520900F89931									
年 月 日 時 分 秒 車種 型式 登録区分 重量 長さ 幅 高さ 最大積重量									