

2014 Daihatsu Move L SA

OVERALL

3.5

EXTERIOR

INTERIOR

MODEL CODE

DBA-LA100S

DISPLACEMENT

658 cc

YEAR / REG.

2014/02

MILEAGE

89,750 km

DOORS

5

SEATS

4

DRIVETRAIN

2WD (FF)

TRANSMISSION

AT

FUEL

Petrol

STEERING

Right

EXTERIOR COLOR

Pink

BODY TYPE

Kei

CHASSIS NO.

LA100S-1072394

DIMENSIONS (L X W X H)

340 × 148 × 162 cm

SALES POINTS

Pre-Collision Braking

INSPECTOR REPORT

Exterior needs repairs. Interior has some noticeable stains. No frame damage.

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 2月		メーカー ダイハツ		ドア枚数 5		ボディ形状 軽四		評価点 3.5					
		車名 ムーヴ		グレード L S A									
車種 自家用		輸入国 右		型式 DBA-LA100S		排気量 660		燃料 ガソリン		内装 C			
車検 9年2月 抹消		走行 89,750 km		C内記マークを記入 (※: 変換 # : 不明) 89 750		駆動 2WD		変速機 AC		安全装置 K			
外装色 ピンク		カラーNo. ベージュ		リサイクル料 8,490円		車台番号 LA100S-1072394		長さ 339 cm		高さ 147 cm		幅 162 cm	
() 登録番号 () 内記 ベージュ		内装色 ベージュ		シフト CVT		乗車定員 4人		乗高 147 cm		乗重 162 cm			

後日返却品 (保証書・取扱説明書等)

装備

☒ ②V ☒ AW ☒ ウォルフ ☒ ②シート
☒ ②B ☒ ナビ ☒ TV ☒ ②C

セールスポイント

CD/フルフラット/横滑り防止装置 (E S C) / 横転防止エアバック/後部座席シートベルト/エアバック/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ベンチシート/デュージュックプレーヤー接続可

常記記入欄

※ダメージレベルに関する注意事項

傷小は記号のみ
 例
 ②B → A
 ②C → A → [1]
 ②B → A → A2
 ②B → A → A → A2

クオリティグレード説明

外装: 補修を必要とする車種です。
 内装: 気になる汚れ等があります。
 後部座席: 骨格部位に異常はありません。

車体状態の確認は、静止状態で実施できる範囲で行います。

車体状態の確認は、静止状態で実施できる範囲で行います。