

2014 SUBARU Exiga 2.5i Spec.B EyeSight		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-YAM	DISPLACEMENT 2,498 cc		
YEAR / REG. 2014/03	MILEAGE 31,640 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Minivan		
CHASSIS NO. YAM-012516	DIMENSIONS (L X W X H) 474 × 178 × 165 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Alcantara, Leather) Adaptive Cruise Control		Power Seats (Front) Pre-Collision Braking	
INSPECTOR REPORT			
Front underbody scrapes, driver's power window switch malfunction			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 3月	メーカー スバル	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価値 4.5
車名 エクシーガ	グレード 2.5i Spec.B アイサイト 社外ディスプレイオーディオ・Bカメラ・ETC・STIリッパ	駆動区分 2WD	④D	
車歴 自用・その他 ()	2500 cc	型式 DBA-YAM	通称 正式	内装 A・⑥・C
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日選り込み (保証書・取扱説明書 等)	
走行 31,640 km	シフト フロア CVT	エアコン	故障品のみ O印 を記入	
外装色 パールホワイト (37)	カラーNo.	AG・⑥・WG・ ()	乗車定員 7 人	
内装色 ()	車検 3月	14,650円	エレクトリック	ナビ TV
セールスポイント パワーシート/3列シート/フルフラット/バックカメラ/ETC/横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/エアロパーツ				
検査記入欄 F底ガリ傷 D席PWスイッチ不良				
車体番号 YAM-012516				
修理歴 有・⑤				
A キズ U ヘッドランプ B キズ・ヘッド P 熱劣化・サビ Q ガラスキズ W 経年劣化 S サビ C 腐食 X 交換済 YX 交換済 登録No. 月 日 までに変更できる方 名 査 中				
車体重量 kg				