

2014 SUBARU Forester 2.0XT EyeSight Advantage Line		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-SJG	DISPLACEMENT 1,998 cc		
YEAR / REG. 2014/07	MILEAGE 104,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. SJG-023557	DIMENSIONS (L X W X H) 460 × 180 × 170 cm		
SALES POINTS			
Alloy Wheels Navigation System		Adaptive Cruise Control	
INSPECTOR REPORT			
Interior dirt/scuffs, seat tears, left side turn signal lens cracked, minor mirror scratches, many minor exterior scratches, underbody rust, headliner dirt, seat glue marks, weak AC cooling			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H26/7	メーカー スバル	ドア枚数 5	ボディタイプ SUV/クロカン	評価点 4
車名 フォレスター	グレード 2.0XTアイサイトアドバンテージライン	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他()	排気量 2000 cc	型式 DBA-SJG	選別形式	内装 A・B・C
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日選り品(保証書・取扱説明書等)	
走行 104,000 km	フロア	AT		
外装色 ブラック	カラーNo.	エアコン	新着品のみ O印 を記入	
()	色番号は()内に「色号」を記入	乗車定員 5人	サンルーフ	
小・中・大 左・右 左・右	輸入 ディーラー	走行 13,010 km	エアロック	スライド
セールスポイント				
スマートキー ハーフレザーシート SDナビ ワンセグ ETC 前後フォグ パドルシフト ウインカーミラー 純正AW				
検査記入欄				
内装汚れ・スレ シート汚れ サイドウインカーレンズ汚れ(点) ミラーA 外装等傷 下回り 足回りの汚れ シートノリ等 AC動作確認				
車体番号 SJG-023557				
修理歴 有・無				
A キズ U ヘコみ/サレ B キズ・ヘコみ P 色あせ/ボケ Q ガラスキズ W 腐蝕品 S サビ C 腐食 X 交換品 YX 交換品				
売却No. 月 日 までに希望できる方				
車体重量 kg				
FW トポ石 フレ 外装 小 ホイル エアロ シリアル No. ④・曲 ④・フレ				
内装 ③④ ③④ ③④ コグス オーディオA ④⑤				