

2014 Honda ACCORD HYBRID LX		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-CR6	DISPLACEMENT 1,993 cc		
YEAR / REG. 2014/01	MILEAGE 54,541 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Sedan		
CHASSIS NO. CR6-1012413	DIMENSIONS (L X W X H) 492 × 185 × 147 cm		
SALES POINTS			
Alloy Wheels Cruise Control Navigation System		Power Seats (Front) Back Camera	
INSPECTOR REPORT			
USS rating 4. Interior has some dirt and scratches. Wheels and door mirrors scratched.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26/1月	メーカー ホンダ	ドア枚数 4	ボディ形状 セダン	評価点 4
車名 アコードハイブリッド	グレード L X	駆動区分 2WD 4WD		
車歴 自家用・その他 ()	排気量 2000 cc	型式 DAA-CR6	通称 2WD	内装 A・B・C
車検 - - 年 月 / 日	燃料 ハイブリッド	ディーゼル ()	後日送付品 (保証書・取扱説明書 等)	
走行 54,541 km	フロア AT			
外装色 ブラック	カラーNo. (NH812P)	AG・BG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	ABS	サンルーフ	革シート
左・右 左・右	ディーラー 13,370円	ABS	キーレス	
セールスポイント 純正インターナビ、フルセグTV、バックモニター、ビルトインETC、スマートキー、プッシュスタート、LEDヘッドライト、クルーズコントロール、パワーシート、				
検査記入欄 USS評価点4点、ルーム内一部汚れキズ、ホイール、ドアミラーキズ				
車体番号 CR6-1012413				
修理歴 有・無				
A キズ U ヘッドランプ B キズ・ヘッド P 前後バンパー Q ガラスキズ W 後部鏡 S サブ C 腐食 X 交換済 YX 交換済 登録No. 月 日 までに名義できる方 名義中 車体番号 CR6-1012413				
内装 革	シス ヤブ	コグ コグ	コグ コグ	コグ コグ