

2014 Honda FIT 13GF Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
GK3	1,317 cc		
YEAR / REG.	MILEAGE		
2014/08	94,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GK3-1048694	396 × 170 × 153 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Exterior has noticeable scratches and dents. Interior has some noticeable stains. There are signs of impact to the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレード鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H26/8月	メーカー ホンダ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 フィット	グレード 13G・Fパッケージ			
車種 自家用	型式 GK3	総排気量 1300	燃料 ガソリン	内装 B
年 9年8月	走行 94,000km	マイル 94,000	エンジン AC	重量 Kg
外装色 クリスタルブラックパール	カラーNo. ()	リサイクル料 9,880円	車両番号 GK3-1048694	
シフト フロア	AT	5人	長さ cm	高さ cm

後付品
(保証書・取扱説明書等)

装備
AW サルーフシート
セーリングポイント

CD/フルフラット傾斜防止装置(E5C) / 運転席エアバック/座席防止システム/スマートキー/カーレスエントリー(A8S) / 助手席エアバック/メモリーナビ/ワンセグTV/衝突安全ボディ/アイドリングストップ/VD再生/ミュージックプレーヤー/後部カメラ

査定員記入欄

※ダメージレベルに関する注意事項
傷は軽微のため
小傷は1
中傷は2
大傷は3
※ダメージレベルはA
※ダメージレベルはB
※ダメージレベルはC
※ダメージレベルはD
※ダメージレベルはE

クオリティグレード説明
外装: 気になるようなキズやヘコミがあります。
内装: 気になる汚れ等が、部分的にあります。
修復歴: 骨格部位に衝撃を受けた形跡があります。

車両状態の検定は、停止状態で実施できる範囲で行っています。