

2014 Honda N-BOX 660 Custom G A Package		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF1	DISPLACEMENT 658 cc		
YEAR / REG. 2014/05	MILEAGE 127,206 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Kei		
CHASSIS NO. JF1-1441576	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Seat wear, carpet stains, front cross member damage, large paint crack on left side spoiler, right mirror scratch, underbody scrapes, dents, and rust. Front windshield has stone chips. Left and right headlights are cloudy/dull. Seat covers are installed. Shift knob, carpet, and other interior trim show scuffs, scratches, and wrinkles. Door mirrors have scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H26/5月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 3
車名 N-BOX	グレード 660 カスタムGAパッケージ 社外ナビ Bluetooth パック カメラ ETC	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-JF1	通称 軽四	内装 A・B・C
車検 9年7月	燃料 ガソリン	ディーゼル ハイブリッド ()	備付選り品 (保証書・取扱説明書 等)	
走行 12,720 km	シフト インパネ	CVT		
外装色 ブラックパール	カラーNo. ()	内装色 ()	新着品のみ O印 を記入	
左・右 左・右	ディーラー 左・右	走行 左・右	AW	サンルーフ
左・右	左・右	左・右	TV	キーレス
セールスポイント 社外ナビ、Bluetooth、Bカメラ、ETC、片電S、エンタ				
検査記入欄 シートすれ、カーベツ汚れ、フロントクロスメンバー損傷、左 サイドスボイラー塗装剥れ大、右ミラーきず、下回りすり・へこ み・錆、フロントウィンドウ隅び石痕、左右ヘッドライト曇り・ くすみ、シートカバー装飾、シフトノブすれ・きず、カーベツ しわ・すれ・きず、他トリムしわ・すれ・きず、ドアミラーキズ				
車検 JF1-1441576				
車検 No.				
車検 No.				