

2014 Honda ODYSSEY 2.4 Absolute		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-RC1	2,356 cc		
YEAR / REG.	MILEAGE		
2014	81,000 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
RC1-1037159	483 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Drive...	
Pre-Collision Braking		Cruise Control	
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor scratches and dents in various areas, on rear bumper, and on floor.			

初年度登録		メーカー		ドア枚数		ボディバックス		特価点																																								
H26 / 一月		ホンダ		5		ミニバンワンボックス		R																																								
		オデッセイ		2.4アブソルート 純正8インチナビ Bluetooth パック カメラ		駆動方式 2WD 4WD																																										
車種	自家用 ・ その他 ()		排気量	2400 CC	型式	DBA-RC1		内装	色 A ⑤・C																																							
年式	- 年 月 日		燃料	ガソリン	ディーゼル	償還月利 (保証率・取扱説明書等)																																										
走行	口印にマーク付与記入(車・交換) (色・点検) (車・点検) 81,000 km		シフト	インパネ CVT																																												
外装色	ブラックパール		カラーNo.	QD・AAD・WAG・()		新価格のみ O印 を記入																																										
()	内装色		標準定員	7人		PS	⑦	④	サンルーフ	革シート																																						
シリン	左・右	輸入区分	ディーラー	走行	14,420円	エアバック	⑧	ナビ	TV	⑨																																						
セールスポイント																																																
検査記入欄						⑤・無																																										
各所A,U R1A1 81,000円A,U						<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>へこみ/サビ</td> <td>B</td> <td>キズ・へこみ</td> <td>P</td> <td>色あせ・めがけ</td> <td>G</td> <td>ガラスキズ</td> </tr> <tr> <td>W</td> <td>傷跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> <tr> <td colspan="9"> 登録No. 月 日 名義 </td> </tr> <tr> <td colspan="9"> 車体番号 R.C1-1037159 </td> </tr> </table>					A	キズ	U	へこみ/サビ	B	キズ・へこみ	P	色あせ・めがけ	G	ガラスキズ	W	傷跡	S	サビ	C	腐食	X	交換済	XX	交換済	登録No. 月 日 名義									車体番号 R.C1-1037159								
A	キズ	U	へこみ/サビ	B	キズ・へこみ	P	色あせ・めがけ	G	ガラスキズ																																							
W	傷跡	S	サビ	C	腐食	X	交換済	XX	交換済																																							
登録No. 月 日 名義																																																
車体番号 R.C1-1037159																																																
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>FW</td> <td>トピ石</td> <td>漏A</td> <td>ワレ</td> <td>外装</td> <td>小</td> <td>ホイル</td> <td>エアロ</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td>⑩・⑪</td> <td>⑫・⑬</td> <td>⑭・⑮</td> </tr> <tr> <td>内装</td> <td>⑯</td> <td>⑰</td> <td>ヤブレ</td> <td>コガ</td> <td>コガス</td> <td>オーデイオス</td> <td>⑱</td> </tr> </table>						FW	トピ石	漏A	ワレ	外装	小	ホイル	エアロ						⑩・⑪	⑫・⑬	⑭・⑮	内装	⑯	⑰	ヤブレ	コガ	コガス	オーデイオス	⑱	最大積載量																		
FW	トピ石	漏A	ワレ	外装	小	ホイル	エアロ																																									
					⑩・⑪	⑫・⑬	⑭・⑮																																									
内装	⑯	⑰	ヤブレ	コガ	コガス	オーデイオス	⑱																																									