

2014 Honda Odyssey Absolute		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RC1	DISPLACEMENT 2,356 cc		
YEAR / REG. 2014/01	MILEAGE 130,141 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. RC1-1006254	DIMENSIONS (L X W X H) 483 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Leather Seats Navigation System	
INSPECTOR REPORT			
Seat edge wear, paint unevenness, door mirror scratches, left rear fender with significant damage.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 1月	メーカー ホンダ	ドア枚数 5	ボディ形状 ミニバンワンボックス	評価値 3.5					
車種 自家用・その他 ()	車名 オデッセイ	グレード アブソルート	駆動区分 2WD 4WD	内装 A・B・C					
排気量 2400	型式 DBA-RC1	燃料 ガソリン	ディーゼル	後付部品 (保証書・取扱説明書等)					
年 13	月 01	日 14	走行 130,141	AT					
外装色 ブラック	カラーNo. (NH731P)	エアコン	AG・AG・WAG ()	装備品のみ O印 を記入					
内装色 ()	乗車定員 8人	リサイクル料	14,420円	預託金					
左・前・後 ディーラー・走行	リサイクル料	14,420円	エアクリーナー	ABS					
セールスポイント									
あんしんパッケージ、両側パワースライドドア、後席モニター (フリップダウン)、メーカーナビ、フルセグTV、ハーフレッジャーシート、ビルトインETC									
検査記入欄									
シートフチヘタリ、Pムラ、ドアミラーキズ、左RフェンダーXX									
修理歴									
有・無									
A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・汚れ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
登録No.					名義中				
月					日				
車体番号					RC1-1006254				
FW	トビ石	傷A	ワレ	外装	小	ホイル	エアロ	シリアル	No.
内装	シロ	ヤブレ	コガ	コガ	コガ	オーディオ	取組	長さ	最大積重量