

2014 Honda ODYSSEY Absolute		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE RC1	DISPLACEMENT 2,356 cc		
YEAR / REG. 2014/01	MILEAGE 125,778 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. RC1-1014215	DIMENSIONS (L X W X H) 483 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels Cruise Control Rear Seat Entertainment (9-inch Wide V...		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Slight interior dirt, engine oil seepage			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 1月	メーカー ホンダ	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価点 4
車名 オデッセイ	グレード アブソルート	駆動区分 2WD 4WD		
車歴 自用・その他 ()	排気量 2400 cc	型式 RC1	通称 RC1	内装 A・B・C
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)	
走行 125,778 km	フロア	AT		
外装色 クリスタルブラックパール	カラーNo. QD・AAG・WAG・ ()	乗車定員 7人	装備品のみ O印 を記入	
左・前・後 14,420円	ディーラー 14,420円	走行 14,420円	エブリック	サンルーフ
セールスポイント				
3列シート/CD/ウオークスルー/バックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/オートクルーズコントロール/オートマン/DVD再生/ミュージックプレイヤー/接続可/後席モニター/両側電動スライドドア				
検査記入欄				
室内薄汚れ エンジンオイルにじみ				
車体番号 RC1-1014215				
修理歴 有・無				
A ボディ U ヘッドライト B キズ・ヘコみ P 熱気・サビ Q ガラスキズ W 経年劣化 S サイズ C 腐食 X 交換部 YX 交換済 登録No. 月 日 まで名義できる方 名義中 車体番号 RC1-1014215				
内装 トヨタ シェ ヴェル コグ コグス オーディオ スレ				
車体重量 kg				