

2014 SUBARU Impreza Sport 1.6i-L		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
GP3	1,599 cc		
YEAR / REG.	MILEAGE		
2014/01	104,940 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GP3-013689	442 × 174 × 147 cm		
SALES POINTS			
Alloy Wheels		STI	
Navigation System			
INSPECTOR REPORT			
AC failure. Exterior has noticeable scratches and dents. Interior condition is not a priority for this vehicle. Evidence of impact near the front or rear frame sections.			

ORIGINAL JAPANESE AUCTION SHEET

青森内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H26/1月	メーカー スバル	ドア数 5	ボディ形状 コンパクトハッチバック	評価点 R
車名 インプレッサスポーツ	グレード 1.6 i-L			
車種 自家用	右	型式 GP3	排気量 1600	燃料 ガソリン
年 10	月 4	日 9	4WD	AC
水色 パール	カラーNo. ()	リサイクル料 12,030円	車台番号 GP3-013689	重量 Kg
シフト フロア 5 MT	乗車定員 5人	長さ cm	幅 cm	高さ cm

後口送り法
(保証書・取扱説明書等)

装備
① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿

セールスポイント
バックカメラ/TC/運転席エアバック/スマートキー/キーレスエントリー/ABS/助手席エアバック/4WD/エアロパーツ

査定員記入欄
AC不良

ボグメージレベルに関する注意事項
F-1
車は1
車は2
車は3
ボグメージレベルに関する注意事項
F-1
車は1
車は2
車は3

クオリティグレード説明
外装: 気になるようなキズやヘコミがありません。
内装: 内装を気にしない方向けのお車です。
修復歴: 骨格部位の先滅付。または後端付近に衝撃を受けた形跡があります。

車体状態の図解
D2412610302

車体状態の図解
D2412610302