

2014 SUBARU Levorg 1.6GT-S EyeSight		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-VM4	DISPLACEMENT 1,599 cc		
YEAR / REG. 2014/10	MILEAGE 85,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Hatchback		
CHASSIS NO. VM4-022166	DIMENSIONS (L X W X H) 469 × 178 × 149 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Cruise Control		Power Seats (Front) Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Light dirt and scuffs on interior, left core support replaced, steering wheel scuffs, seat scuffs, right power folding mirror faulty, 1 scratch on front glass.			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 H26 10月	メーカー スバル	ドア数 5	ボディタイプ コンパクト/ハッチバック	評価点 3.5
車名 レヴォーグ	グレード 1.6GT-Sアイサイト	駆動方式 2WD	燃費区分 490	
車種 乗用車・その他()	排気量 1600 cc	型式 DBA-VM4	通称 2WD	内装 A・B・C
車検 - 年 月	燃料 ガソリン	ディーゼル	後付部品 (保証書・取扱説明書 等)	
走行 85,000 km	シフト フロア AT			
外装色 グレー	カラーNo. ()	エンジン AG・AG0・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	エアコン	サンルーフ	寒シート
リフト 左・右	ディーラー ・ 走行	13,610円	エレクトロ	TV
セールスポイント				
スマートキー SDナビ Bカメラ ETC 前後ドラレコ ウインカーミラー 純正AW				
検査記入欄				
内装汚れ・スレ 左コサボート交換 ハンドルスレ シートスレ 右電動格納ミラー不良 F点点検!				
修復歴 有・無				
A キズ B ハミ・ヒビ C キズ・へこみ D 色あせ・ボケ E ガラスキズ W 経年劣化 S サビ C 腐食 X 交換部 XX 交換済				
名義中 月 日 まで名義できる方				
車検 No. VM4-022166				
内装 トビ石 シス ヤブレ コガ コガス オーディオス				
車検 No. VM4-022166				
車検 No. VM4-022166				