

2014 Lexus GS 3.5 GS350 I Package 4WD		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-GRL15	3,456 cc		
YEAR / REG.	MILEAGE		
2014/03	42,139 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GRL15-6000917	485 × 184 × 147 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Seats (Front)		Cruise Control	
Back Camera		Navigation System	
Lexus GS Premium Sound System (12 s...			
INSPECTOR REPORT			
Exterior has minor scratches and dents. Wheels have scratches. Seats have stains and scuffs. Steering wheel has scuffs. Front windshield has scratches, stone chips, cracks, and repair marks, requiring replacement. Interior has scratches, stains, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成26年 3月		車名・グレード GS GS350Iパッケージ		2WD (4WD)		評 価 点 (4.5)	
ディーラー・並行 型式 DBA-GRL15		排気量 3500		ドア 4		定員 5人	
モデル年式 年 ハンドル 左・右		形状 SD		積載 kg		外 装 内 装 B B	
車種 自家用		シフト FAT		セールスポイント (正常に機能するものに限りです)			
車検 令和9年 3月 (日)		冷暖 AAC		スマートキー・ETC・HIDヘッドライト			
走行 4万2千139 km		燃料 ガソリン		左右シートヒーター 左右パワーシート			
色 シルバー		色コード 1J2/LC20		諸備品 (純正品に限り○をつけてください)			
R券 13,940 円				(PS) (PW) (BS) (AB) (AW) SR ナビ TV カワ			
注意事項申告欄				新車保証書 有・無			
外装 小A・小U							
ホイル キズ							
シート 汚れ							
シート すれ							
ハンドル すれ							
フロントガラス キズ・傷・ヒビ割・リペア跡・X要				A・キズ E・エウボ U・凹み W・補修跡 S・サビ C・腐食 XX・交換済			
内装 キズ・傷・ヒビ割・コゲ・穴・変色・キレ・破れ				型式指定番号 17073			
車台番号 6000917				車検区分番号 0015			
登録番号 新潟 309 ち 111				全長 485			
				全幅 184			
				全高 147			