

2014 Lexus GS 350 F Sport		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-GRL10		DISPLACEMENT 3,456 cc	
YEAR / REG. 2014		MILEAGE 174,000 km	
DOORS 4		SEATS 5	
DRIVETRAIN 2WD (FR)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR White		BODY TYPE Sedan	
CHASSIS NO. GRL10-6004559		DIMENSIONS (L X W X H) 485 × 184 × 145 cm	
SALES POINTS			
Alloy Wheels Leather Seats (Leather) Back Camera Lexus GS Premium Sound System (12 s...		Power Seats (Front) Cruise Control Navigation System	
INSPECTOR REPORT			
Scratches on hood, cracks on front bumper, scuffs on lower front bumper, scratches on right side sill, undercarriage impact damage, minor scratches on right rear door edge, scuffs on all wheels, scratches on rear bumper, minor scratches on left rear fender, rust on left front fender, some black stains on seat. *Please note that issues with preventative maintenance items (consumables, etc.) are not covered.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H26	メーカー レクサス	ドア数 2	ボディ形状 セダン	評価点 3.5
車種 自家用	グレード G S	350 Fスポーツ	駆動方式 4WD	
型式 DBA-GRL10	排気量 3450 cc	変速機 AT	内装 A・B・C	
走行 174,000 km	燃料 ガソリン	ディーゼル	後付選用品 (保証書・取扱説明書等)	
外装色 ホワイトノヴァガラスフレック	カラーNo. ()	エンジン (G・AAG・WAG・)	新車品のみ・O印を記入	
内装色 ()	車庫定員 人	PS PS	PW PW	AW AW
左・前 左・前	ディーラー ディーラー	走行 12,790 km	エアバック ABS	サンルーフ TV
キーレス				
セールスポイント				
検査記入欄				
ボンネットに傷、フロントバンパーに割れ、フロントバンパー下部に擦り傷、右サイドシルに傷、下面りに突起、右リアドアエッジに小傷、全アルにガリ傷、リアバンパーに傷、左リアフェンダーに小傷、左フロントフェンダーに錆び、シートの一部腐すみ ※本車同に対する予防整備(消耗品等)の不具合、劣化等に関しては免責事項となります。				
名義中				
月 日				
GRL10-6004559				
485 184 145				