

2014 MAZDA ATENZA SEDAN XD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GJ2FP	DISPLACEMENT 2,188 cc		
YEAR / REG. 2014/01	MILEAGE 89,530 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Sedan		
CHASSIS NO. GJ2FP-108681	DIMENSIONS (L X W X H) 486 × 184 × 145 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control		Cruise Control Navigation System	
INSPECTOR REPORT			
Exterior: There are noticeable scratches and dents. Interior: There are noticeable stains. Repair history: No abnormalities in the frame.			

青肉内のグレー鑑定/JAAA鑑定証の調べと下記記載の評価は真なりです 前年登録 1月		メーカー マツダ		ドア枚数 4		ボディ形状 セダン		評価点 4	
H26/		車名 アテンザセダン		グレード X D					
車種 自家用		型式 右		型式 GJ2FP		年式 2200		燃料 ディーゼル	
年式 9 年 1 月 / 抹消		走行距離 (100kmマーカーを記入) (注: 交換 ※ 遠方) (※ マイル) 89,530		車庫 AC					
外装色 レッド		カラーNo. リサイクル料		12,420円 * 販売店		車両番号 GJ 2FP-108681			
() (保証書は1年内に有効と記入)		シフト フロア 6 AT		乗車定員 5 人		長さ cm		幅 cm	
旅行口送り (保証書・取説説明書等)				車庫内保管状態 (車庫内保管状態を記入) (注: 車庫内保管状態を記入) (注: 車庫内保管状態を記入)		グレー鑑定機関認定 (車庫内保管状態を記入) (注: 車庫内保管状態を記入) (注: 車庫内保管状態を記入)			
装備		グレー鑑定 コンディションチェックシート		R06126E2205					
③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿		セールスポイント		車庫内保管状態					
ナビTV パックカメラ ETC レーダークラスコントロール オートライト 純正19アルミホイール		査定員記入欄		車庫内保管状態					
※ボデーメーゼルに関する注意事項		車庫内保管状態		車庫内保管状態					
車庫内保管状態		車庫内保管状態		車庫内保管状態					
クオリティグレード説明		車庫内保管状態		車庫内保管状態					
外装: 気にならぬようなキズやオモミがあります。		車庫内保管状態		車庫内保管状態					
内装: 気になぬ汚れ等があります。		車庫内保管状態		車庫内保管状態					
修復歴: 骨格部位に異常はありません。		車庫内保管状態		車庫内保管状態					
車庫内保管状態		車庫内保管状態		車庫内保管状態					