

2014 MAZDA Axela Sport 15S		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE BM5FS	DISPLACEMENT 1,496 cc		
YEAR / REG. 2014/03	MILEAGE 115,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Hatchback		
CHASSIS NO. BM5FS-103856	DIMENSIONS (L X W X H) 446 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior: There are noticeable scratches and dents. Interior: There are noticeable stains. Repair history: There are signs of impact near the front or rear end of the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H26/3月	メーカー マツダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 R
車名 アクセラスポーツ	グレード 15S			
車種 自家用	型式 右	型式 BMSFS	総排気量 1500	燃料 ガソリン
年 11	月 15	日 00	走行 10,770 km	AC
外装色 チタニウムフラッシュマイカ	カラーNo. ()	リサイクル料 10,770円	車両番号 BMSFS-103856	重量 Kg
シフト フロア 6 MT	乗車定員 5人	長さ cm	幅 cm	高さ cm

後付品
(保証書・取扱説明書等)

装備
CD/バックカメラETC/横滑り防止装置(ESC)/HID・キセノン・ディスチャージ/運転席エアバック/座席側エアバック/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/ワンセグTV/衝突安全ボディ/アイドリングストップ/DVD再生

査定員記入欄

※ダメージレベルに関する注意事項
傷は記号のみ
小傷: 1
中傷: 2
大傷: 3
※ダメージレベルはAからEまであり、Aが最も軽微なダメージ、Eが最も重大なダメージを示します。

ボディタイプ
外装: A
内装: B
エンジン: C
変速機: D
駆動方式: E
その他: F

クオリティグレード説明
外装: 気になるようなキズやヘコミがあります。
内装: 気になる汚れ等があります。
修復歴: 骨格部付近の先端付近、または後端付近に衝撃を受けた形跡があります。

車両状態の検閲は、停止状態で実施できる範囲で行っています。