

2014 MAZDA CX-5 XD		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-KE2FW	DISPLACEMENT 2,188 cc		
YEAR / REG. 2014/02	MILEAGE 87,554 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. KE2FW-132534	DIMENSIONS (L X W X H) 454 × 184 × 171 cm		
SALES POINTS			
Alloy Wheels Cruise Control Back Camera		Pre-Collision Braking Side Camera Navigation System	
INSPECTOR REPORT			
Left power mirror faulty, right power mirror cover cracked, rear headrest center missing/damaged.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26 / 2月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クワカン	評価点 4.5
車名 CX-5	グレード XD 社外ナビ・フルセグ・S/Bカメラ・ETC・クルコン	駆動区分 4WD	4WD	
車歴 自家用・その他 ()	排気量 2200 CC	型式 LDA-KE2FW	通称 2WD	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	デジ ハイブリッド ()	後日進引品 (保証書・取扱説明書 等)	
走行 87,554 km	シフト フロア 6 AT	モーター AG・BG・WAG・ ()	故障品のみ O印 を記入	
外装色 パールホワイト (34K)	内装色 ()	乗車定員 5 人	サンルーフ	革シート
左・前 左・前	ディーラー ディーラー	走行 11,650 km	エブリック	ス
セールスポイント CD/バックカメラ/TC/横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ他/フルセグTV/衝突安全ボディ/アイドリングストップ/ターボ/オートクルーズコントロール/DVD再生				
検査記入欄 左電格ミラー不良 右電格ミラーカバー割れ リアヘッドレスト真ん中欠				
修理歴 有 ()				
A キズ U ヘッドランプ B キズ・ヘッド P 熱劣化・サケ Q ガラスキズ W 経年劣化 S サビ C 腐食 X 交換品 XX 交換済 車検No. 月 日 までに名義できる方 車体番号 KE2FW-132534				
FR トボ石 傷A フレ 外装 小 ホイル エアロ ()・U A・曲 A・フレ	シリアル No.			
内装 ヨゴレ シス ヤブレ コグ コグ穴 オーディオ スレ	長さ cm	幅 cm	高さ cm	最大重量 kg