


2014 MINI Crossover Cooper		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
CBA-ZA16	1,598 cc		
YEAR / REG.	MILEAGE		
2014/06	69,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMWZB32040WR87552	411 × 179 × 155 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Minor scratches throughout, minor interior dirt, minor alloy wheel scratches			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H26/6月	メーカー MINI	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4
車名 MINI	グレード クーパー/ナビ バックカメラ フルセグTV	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1600 cc	型式 CBA-ZA16	通称 A・C	内装 A・C
年 6	月 6	日 6	燃料 ハイブリッド	ディーゼル ()
走行 69,000 km	シフト フロア 6 AT	後日送り品 (保証書・取扱説明書等)		
外装色 ダークブルーホワイトツートン	カラーNo. ()	エアコン AG・QG・WAG・()	新車品のみ O印 を記入	
内装色 ()	乗車定員 5 人	PS PS PS PS PS	サンルーフ ()	革シート ()
ハンド 左・右	輸入 区分	走行 17,490 円	エレクト ()	ABS ()
セールスポイント ☆ナビ ☆フルセグTV ☆バックカメラ ☆Bluetoothオーディオ ☆DVD再生 ☆オートキセノンライト ☆プッシュスタート ☆ETC ☆ホワイトルーフ				
検査記入欄 各キズ 小 内装汚れ 小 AWキズ 小		修復歴 有・無 A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ G ガラスキズ W 補修部 S サビ C 腐食 X 交換部 XX 交換済 登録No. 月 日 までに名変できる方 車体番号 WMWZB32040WR87552		
FW (トビ)	備A シシ	ワレ ヤブレ	外装 小 A・U A・曲 A・ワレ	エアロ No.
内装 (ヨシ)	シシ	ヤブレ	コガ コガ穴 オーディオ穴 スレ	シリアル No.
長さ cm	幅 cm	高さ cm	最大積載量 kg	