

2014 MITSUBISHI Delica D2 S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-MB15S	1,242 cc		
YEAR / REG.	MILEAGE		
2014/05	99,000 km		
DOORS	SEATS		
5	5		
TRANSMISSION	FUEL		
AT	Petrol		
STEERING	EXTERIOR COLOR		
Right	Black		
BODY TYPE			
Hatchback			
CHASSIS NO.	DIMENSIONS (L X W X H)		
MB15S-254101	371 × 162 × 177 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
INSPECTOR REPORT			
Interior dirt and scuffs, seat tear, multiple exterior panel repairs, rocker cover X, bumper scratches, stereo hole, extensive W2 damage, touch-up paint present, slight front door bumper misalignment, rear sun visor deformed/cracked, front and rear tire wheel minor damage.			

[illegible]